


**Figure 5. Three dimensional image from ArcScene detailing a sample of the partially processed upstream Study site surface.**



**Figure 6. Three dimensional image from ArcScene detailing a sample of the partially processed upstream Study site surface. Examples of potentially erroneous bathymetric sonar returns are identified in in red.**